

Subject : Clutch cable checking.

Dear Customers,

We ask you to pay attention about your C2R2 clutch cable. Thank you to do a check on both areas shown on the pictures below.

If one of these areas (or both) are like the pictures, please send it at the following adress :

CITROËN Sport
A l'attention de Mr François DOUNIAUX
19 Allée des Marronniers BP 3557,
78035 VERSAILLES Cedex
France.



On pedal side, end of sheath stop area



On pedal side, fixing of the sheath area

After our check, all part judged failed or risky will be sent to you, free of charge.

Nota :

- CITROËN Sport will take the final decision to replace cables or not. We will never accept cables in bad conditions, destroyed or used.
- This infotech don't replace infotechs N° 30 and 31, the reliability of the clutch command will be OK only if the job explained in both infotechs is done with rigour.

Thank you for your attention.

S. BARRAUD, le 27/09/07